



Tuesday, June 23, 2015

## Load Cell Calibration

### Calibration Procedure,

We will test all system components [TorqueView™ Controller, remote display, load cell] and included cables. We will calibrate the torqueView™ Controller if necessary. Finally, we will do an end-to-end calibration and issue a traceable certificate.

Shipping instruction, follow the following suggestion so the equipment is not damaged in shipping,

1. Package the load cell separately, even if all equipment is shipped in the same box.
2. Make sure the Remote Box & Display are bubble wrapped properly.
3. Tie all cables together.
4. Use a heavy duty shipping box or optionally use our shipping transportation case.

### Ship to address,

1718 Fry Rd. Suite 420  
Houston, Texas 77084  
(281) 698-8031

### Needed items,

1. Load Cell
2. Torque Turn System [TorqueView™ Remote box, m System Touch™, Instrumentation Card or FORCEmon™ Remote]
3. TorqueView™ Display
4. Cables [Load Cell, Remote Box, A/C, Computer, Remote Display]
5. Specify the certificates duration [i.e. 3 month, 6 month, 1 year or other].
6. Purchase Order & Billing Info
7. Contact Info [Phone #, Email]
8. Shipping address and any shipping preferences. We normally insure and ship via UPS.
9. Calibration normally takes 3-5 days base on the load cell size & style. Let us know if you want to expedite calibration.

Regards,

Y:\Project's\Torque View\User Manuals\torqueView Calibration info. 06232015-01.doc

Anthelion Systems, Inc.

CONFIDENTIAL